PAY ESTIMATE NO. 6

REPAIRS TO MAIN TILE AND LATERAL 3 DD#25 & REPAIRS TO MAIN TILE DD#1, HARDIN CO. PROJECT NUMBER: 6501

DATE: 10-5-20

CONTRACTOR


McDowell and Sons Contractors, Inc. 10214 Hwy 65 Iowa Falls, Iowa 50126

OWNER
Trustees of Drainage District #25 & DD#1
Hardin County Courthouse 1215 Edgington Ave., Suite 1 Eldora, Iowa 50627

ENGINEER
Clapsaddle-Garber Associates
739 Park Avenue
Ackley, Iowa 50601

Item No.	Description	Estimated Quantity	Unit Installed Quantity	Unit <u>Price</u>	Extended Price
	BASE BID ITEMS 24" Ø RCP Tile	260	LF 260	\$ 70.00	\$ 18,200.00
	Type PC-2 Concrete Collar	14	EA 14	\$ 70.00 \$ 500.00	\$ 18,200.00 \$ 7,000.00
	Private Tile Connection	2	EA 2	\$ 600.00	\$ 1,200.00
	Tile Removal	260	LF 260	\$ 10.00	\$ 2,600.00
	Permanent Seeding	0.3	AC 0.3	\$ 3,500.00	\$ 1,050.00
	Seeding Warranty	1	LS 1	\$ 1,000.00	\$ 1,000.00
		1	<u> </u>	ψ 1,000.00	Ψ 1,000.00
	B DIVISION ALTERNATE BID 12" Ø RCP Tile	780	LF 819.9	\$ 38.00	\$ 31,156.20
	24" Ø Steel Casing (Jack & Bore)	0	LF 0	\$ 380.00	\$ -
	12" Ø DIP Tile	0	LF 0	\$ 77.00	\$ -
	Intake Junction Structure	2	$\frac{\text{Er}}{\text{EA}} = \frac{0}{2}$	\$ 1,750.00	\$ 3,500.00
	CCTV Tile Inspection	0	LF 0	\$ 1,730.00	Φ.
	Type PC-2 Concrete Collar	4	$\frac{\text{Er}}{\text{EA}} = \frac{0}{3}$	\$ 350.00	\$ 1,050.00
	Private Tile Connection	4	$\frac{EA}{EA} = \frac{3}{3}$	\$ 600.00	
10/AL1		1	$\frac{EA}{STA} = \frac{3}{0.5}$	\$ 350.00	
	Tile Removal	363	LF 363		
	Tile Abandonment	100	LF 100	\$ 14.00	\$ 1,400.00
	12" Ø Hickenbottom Intake	0	EA0	\$ 1,000.00	\$ -
	RRPermitting,Flagging,Insurance,Coordination	1	LS <u>1</u>	\$ 6,500.00	\$ 6,500.00
	Locate Existing	14.74	STA 14.74	\$ 90.00	\$ 1,326.60
	Intake Removal	0	EA0	\$ 300.00	\$ -
	30" Ø Steel Casing (Jack &	110.5	LF <u>110.5</u>	\$ 560.00	\$ 61,880.00
	18" Ø DIP Tile	135.2	LF <u>135.2</u>	\$ 120.00	\$ 16,224.0
117ALT^^	10" Ø Private Tile Repair	27.8	LF <u>27.8</u>	\$ 25.00	\$ 695.00
LATERAL 3	B DIVISION ADDITIONAL ALTERNATE BI	D			
201ALT**^^	12" Ø RCP Tile	756.3	LF 756.3	\$ 38.00	\$ 28,739.4
202ALT	Type PC-2 Concrete Collar	4	EA 4	\$ 350.00	\$ 1,400.0
203ALT^^	Private Tile Connection	3	EA 2	\$ 600.00	\$ 1,200.0
204ALT	Grading	1	STA 0.5	\$ 350.00	\$ 175.0
205ALT** ^ '	Tile Removal	0	LF 0	\$ 6.00	\$ -
206ALT^^	12" Ø Hickenbottom Intake	0	EA 0	\$ 1,000.00	\$ -
207ALT^^ 1	Locate Existing Lateral Tile	21.2	STA 21.2	\$ 90.00	\$ 1,908.00
208ALT^ (CCTV Mobilization	1	LS 1	\$ 1,530.00	\$ 1,530.00
209ALT^^	10" Ø Private Tile Repair	75.2	LF 75.2	\$ 25.00	\$ 1,880.00
LATERAL 3	B DIVISION SOUTH PORTION BID				
401ALT**	12" Ø RCP Tile	1257	LF 1257	\$ 47.00	\$ 59,079.00
	Type PC-2 Concrete Collar	1	EA 1	\$ 350.00	\$ 350.00
	Tile Removal	5	LF 5	\$ 9.00	\$ 45.00
	5" Ø Private Tile Repair	18.7	LF 18.7	\$ 10.00	\$ 187.00
405ALT^^	Locate Existing Lateral Tile	12.57	STA 12.57	\$ 90.00	\$ 1,131.30
IAIN 1 DIVI	SION RID				
	24" Ø Polypropylene Tile	123	LF 123	\$ 55.00	\$ 6,765.0
	34" Ø Steel Casing (Jack & Bore)	50	LF 50	\$ 707.00	\$ 35,350.00
	22 ½° x 24" Ø Polypropylene Bend	3	$\frac{EI}{EA} = \frac{30}{3}$	\$ 450.00	\$ 1,350.0
	11 ¼° x 24" Ø Polypropylene Bend	1	EA 1	\$ 450.00	\$ 450.0
			EA 1	\$ 1,750.00	
	Intake Junction Structure	1 1			
	Type PC-2 Concrete Collar			\$ 350.00	\$ 350.0
	Private Tile Connection	1		\$ 600.00	\$ 600.0
	Grading	2	STA	\$ 350.00	\$ -
	Tile Removal	49	LF 49	\$ 10.00	\$ 490.0
	Tile Abandonment	58.5	LF <u>58.5</u>	\$ 25.00	\$ 1,462.50
	Traffic Control	1	LS 1	\$ 1,650.00	\$ 1,650.0
	Seeding	0.3	AC <u>0.3</u>	\$ 3,500.00	\$ 1,050.0
	Seeding Warranty 12" Ø Hickenbottom Intake	1	LS 1	\$ 1,000.00	\$ 1,000.00
314	12 Ø FICKEHOOHOM INTAKE	1	EA1	\$ 1,000.00	\$ 1,000.0
I have reviewe	ed the work claimed to be	TOTA	L WORK COMPLI	ETED TO DATE	\$ 309,827.0
completed by the Contractor as reflected				% RETENTION	\$ 30,982.70
above and recommend payment of \$ 3,840.57			AMOUNT DUE LE		
to the Contrac				VIOUSLY PAID	
		_	TRE		
· <u> </u>	Lee Gallentine, Project Engineer		AMOUNT DUE	AT THIS TIME	\$ 3,840.5

Contractor



For pay estimate #2, \$1,845.00 was for DD 25.

For pay estimate #3, \$46,095.75 was for DD 1.

For pay estimate #4, \$56,584.17 was for DD 25.

For pay estimate #4, \$30,364.17 was for DD 25.
For pay estimate #6, \$3,840.57 was for DD 25.
P:\6501\PM\Excel\6501 & 6749.5-Pay Estimates Record.xls

* - Approved as part of Change Order #2
** - Approved as part of Change Order #3 ^ - Approved as part of Change Order #6

^^ - Approved as part of Change Order #7

